TEL: +230 5773 9126



LFC[™] 1B Pressure Regulating Valves

Overview:

A pressure regulating valve is designed to maintain a desired downstream pressure irrespective of the flow requirement. The LFC™_1B fixed ratio pressure regulating valve has been developed to present a robust and simple solution to fluid handling issues in the mining sector.

Simplicity:

The LFC™ 1B pressure regulating valve is designed to minimize wearing parts and in effect only has one moving part called the plug assembly. The plug assembly is a piston that is engineered to be unbalanced. The unbalanced plug assembly is designed to use inline fluid pressure to create specific conditions in the system without the use of an external controller or pilot. A fixed reduction ratio can be established by fixing the surface area ratio exposed to the upstream and downstream pressures. Upstream pressure (Pu) would act to open the valve and downstream pressure (Pd) would act to close the valve. As the Pd increases, the closing force increases proportionally causing the valve to close. If Pd is reduced, the valve will open proportionally in an effort to maintain its hydraulic ratio.



Features:

- Reduced cavitation
- Low noise levels
- Low vibration
- One moving part
- Increased flow capacity
- Long lasting

Recommended ratio lim	its with the V-Port design:	Recommended ratio limit	s with double trim designs:	Recommended ratio limits with triple trim designs:		
Maximum Ratio	Maximum Ratio Pressure (MPa)		Maximum Ratio Pressure (MPa)		Pressure (MPa)	
5:1	0 to 2	12:1	0 to 2	12:1	2 to 4	
4:1	2 to 4	9:1	2 to 4	9:1	4 to 6	
3:1	4 to 6	7:1	4 to 6	6:1	6 to 8	
2.5:1	6 to 8	5:1	6 to 8	5:1	8 to 10	
2:1	8 to 10	4:1	8 to 10	4:1	10 to 12	
1.5:1	10 to 12	3:1	10 to 12			

Selecting Control Valve With Trim Design:

Note! Only in cases where the water / fluid is free from large particles, control valves with trims can be considered. Should there be particles present in the fluid where a trim design control valve was selected, the trim will act as a strainer. Besides potentially impacting the pressure losses across the valve, this can also result in mechanical interference with the plug travel and stop the valve from operating.

Flow Rates:

Flow (ℓ/sec)		5	10	25	35	50	100	150	200	250	300
(кРа)	DN50	17	81								
	DN80	5	35	90							
8	DN100		1,5	30	45	98					
۵	DN150			2,5	6,5	15	57				
an	DN200					2,5	14	42	76		
SS	DN250						7	17	27	46	65
Ä	DN300										
Flow US g	Flow US gallon / min		158.50	396.26	554.76	792.52	1585.03	2377.55	3170.06	3962.58	4755.09
.ii	2"	2.47	11.75								
Pressure Drop (psi)	3"	0.73	5.08	13.05							
	4"		0.22	4.35	6.53	14.21					
	6"			0.36	0.94	2.18	8.27				
	8"		·			0.36	2. 03	6.09	11.02		
	10"		·				1.02	2.47	3.92	6.67	9.43
	12"		·								

TEL: +230 5773 9126
E-MAIL: SALES@HYDROMINE.BIZ
WEBSITE: WWW.HYDROMINE.BIZ
COMPANY NO: 135791 C1/GBL (MAURITIUS)
JURISTAX LTD, LEVEL 3, EBENE HOUSE, HOTEL AVENUE,
33 CYBERCITY, EBENE, 72201, REPUBLIC OF MAURITIUS


LFC[™] 1B Pressure Regulating Valves

Plug Assembly, V-Port And Dealing With Cavitation:


Closed Position



5% Open Position




12% Open Position



30% Open Position



40% Open Position



As displayed, the LFC™ 1B pressure regulating valve plug assembly and movements.

Closed Position: Shows the plug assembly on the body seat in a fully closed valve position.

5% Open Position: Shows the plug assemble in a 5% open position. It can clearly be seen that only the top of the V-Port opens up and creates a flow path. This reduces cavitation and helps with fine control at low flow conditions.

12% Open Position: Shows the plug assembly in the 12% open position. Now it can be observed how the V-Port moved away from the seat and the openings are increasing proportionally. At this point the top of the V-Ports are now being exposed to the flow path.

30% Open Position: Shows the plug assembly in the 30% opened position. Now it can clearly be seen that the full V-Port is creating a larger orifice in the flow path. Up to this point, cavitation needs to be dealt with to increase the life expectancy of the valve. The V-port trim ensures that the seating elements are further apart from each other during low flow allowing the cavitation to take place on noncritical components of the valve.

40% Open Position: Shows the plug assembly in the 40% open position. Now it can clearly be seen that the V-Port is completely away from the seat and the flow path is now relatively large. At this point the flow is approaching its medium demand flow rate and the V-Port has little to no function.

Materials Of Construction:

Part Name	Material Specification				
Body - DN50 to DN100	Casting - 431 S/ Steel				
Body - DN150 to DN400	Casting - BS3100 Grade A2				
Body seat	431 S/ Steel				
Flanges	ASTM A105				
Plug	431 S/ Steel				
V-Port	431 S/ Steel				
Trim	431 S/Steel				
Piston rod	431 S/Steel				
Piston	431 S/ Steel				
Plug seat – 0 to 2,5 MPa	Polyurethane				
Plug seat - above 2, 5 MPa	UHMWPE				
Sleeve (DN150 to DN400)	431 or 304 S/Steel				
Cylinder	431 S/ Steel				
Cylinder holder	Carbon steel				
Seals	Nitrile (Buna)				
O-Rings	Nitrile (Buna)				
Hose	Single braided				

Low Maintenance Requirement:

All the moving parts of LFC $^{\text{TM}}$ _1B pressure control valve are manufactured from stainless steel which increases reliability and durability. The LFC $^{\text{TM}}$ _1B pressure control valve requires minimal maintenance, the majority of which, can be conducted with the valve remaining in situ.

TEL: +230 5773 9126
E-MAIL: SALES@HYDROMINE.BIZ
WEBSITE: WWW.HYDROMINE.BIZ
COMPANY NO: 135791 C1/GBL (MAURITIUS)
JURISTAX LTD, LEVEL 3, EBENE HOUSE, HOTEL AVENUE,
33 CYBERCITY, EBENE, 72201, REPUBLIC OF MAURITIUS

LFC[™]_1B Pressure Regulating Valves

Robust, Reliable and Efficient:

Due to the minimal number of moving parts to effect the fluid control, the number of potential failures are minimized. The valve can only fail for the following reasons:

- 1. Lack of maintenance: If filters are utilized in the control system, regular cleaning of the filters are required to prevent the valve operation from slowing down and eventually creating a possible hydraulic locking of the valve. This process depends on the condition of the service water being used. The dirtier the water, the shorter the filter maintenance intervals will need to be. A valve seal replacement program should be employed to ensure that the valves plug seals are replaced in accordance with manufacturer 's recommendations. As these seals are largely protected the intervals for maintenance on these items can usually be done in terms of years. If these seals fail, the valve will start to bypass pressure from the Pu to the air vent chamber. Valves are equipped with tell-tale breather holes which will immediately indicate seal failure.
- 2. Mechanical fouling: Should a large object be introduced into the service water piping and reach the valve inlet, such object could create a mechanical jam and prevent the plug from operating.
- 3. Overriding of the control system: As the valve is hydraulically actuated and controlled, if the control system is isolated from the service water by way of isolation valves in the control system, the valve will be hydraulically locked in position and will be unable to adjust to the inline condition changes.
- 4. Mechanical failure of the main seating arrangement: In time, the seating arrangement will experience conditions of high velocity across the seating surface during low flow conditions. The high velocity will eventually cause wear on the seating surface and on the plug seating surface. If the valves starts to bypass across its seat, the down stream pressure could increase to the point where the pressure relief valve is activated during low flow conditions.

All of these conditions are easily avoidable and rectifiable through regular maintenance programs and service water quality control and condition monitoring.

Dimensions:

Face to face Dimensions:									Height	
Unit	#300		#600		#900		#1500		Centre line to top of valve	
	(mm)	(inch)	(mm)	(inch)	(mm)	(inch)	(mm)	(inch)	(mm)	(inch)
DN50 / 2"	292	11.50	292	11.50	368	14.49	368	14.49		
DN80 / 3"	356	14.02	356	14.02	381	15.00	470	18.50		
DN100 / 4"	432	17.01	432	17.01	457	17.99	546	21.50		
DN150 / 6"	559	22.01	559	22.01	610	24.02	705	27.76		
DN200 / 8"	660	25.98	660	25.98	737	29.02	832	32.76		
DN250 / 10"	787	30.98	787	30.98	838	32.99	991	39.02		
DN300 / 12"	838	32.99	838	32.99	965	37.99	1130	44.49		
DN350 / 14"	889	35.00	889	35.00	1029	40.51	1257	49.49		
DN400 / 16"	991	39.02	991	39.02	1130	44.49	1384	54.49		

Valve Sizing:

Please consult with Hydromine for clarification of correct sizing for your requirements.

Design & Manufacturing Standards:

The LFC™_1B pressure regulating valve has been designed in accordance with various international standards as set out below:
ASME Boilers and pressure vessels design code
ANSI B16.10ANSI B16.3
ANSI B16.34ANSI B16.37

ANSI B16.5 ANSI N278 .1

Available sizes: DN50 / 2" to DN400 / 16" Face to face dimensions to ANSI B16.10 Pressure rating: up to 25MPa / 3 626 psi

Available end connections: ANSI B16.5, BS4504, BS10, AS/NZS 4331.1 (ISO 7005-1) DIN, Victaulic, HMP $^{\text{TM}}$ Couplings, HMP $^{\text{TM}}$ -TE tapered couplings and other as per clients requirement.